


Water vapor transfer network model building up screen



- Water vapor does not pass through the steel plate. The two nodes on the inner and outer surfaces of the spiral duct is not connected.
- Moisture vapor movement was assumed to be mainly caused by air movement, and moisture conduction through walls, etc. was omitted.
- Water vapor is generated constantly in the bathroom, and intermittent in the bedroom and in the kitchen.